

DIVISION OF OIL, GAS AND MINING Norman H. Bangerter Governor Dee C. Hansen

Executive Director Dianne R. Nielson, Ph.D.
Division Director

Salt Lake City, 1
801-538-5340

# DEPARTMENT OF NATURAL RESOURCES

### **INSPECTION REPORT**

355 West North Temple 3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

Partial: XX Complete: \_\_Exploration\_ Inspection Date/Time: July 13, 1993/08:30am-12:30pm

Date of Last Inspection: June 24, 1993

M 2	Name Chaldra Man Garden Garden	<b>.</b>			1 CM 100M 100F	
UII	ne Name: Skyline Mine County: Carbon	P	ermit N	umber:_	ACT/00//005	
	mittee and/or Operator's Name: Coastal Sta			tan Fue	1	
	siness Address: P. O. Box 719, Helper, UT					
	pe of Mining Activity: Underground XX Suri					
	(icials(s): State: <u>Stephen J. Demczak</u> Co					
Fed	deral Official(s):	<b>leathe</b> :	r Condi	tions:_	Warm 70's	
Exi	sting Acres:Permitted- <u>7067.11</u>	2.08 Re	egraded	-Seeded	- Bonded- <u>62.</u>	41
Inc	creased/Decreased: PermittedDisturbed-	Regi	raded	_Seeded	Bonded	
Sta	tus:Exploration/_X_Active/Inactive/	Temp	Cessat	ion/_E	ond Forfeitu	re
F	Reclamation (Phase I/Phase II/Final B	3ond Re	elease/	Liabi	lity Year	)
T on end	REVIEW OF PERMIT, PERFORMANCE STANDARDS & PI	ERMIT CON	NDITION RE	QUIREMENTS		
	ructions					
1.	Substantiate the elements on this inspection by checking the					
	a. For complete inspections provide narrative justificati			its not ru	ily inspected uni	ess
	element is not appropriate to the site, in which case of b. For partial inspections check only the elements evaluate					
2	Document any noncompliance situation by referencing the NOV	20. Licenso	at the an	nuonnista	anufannana stand	
	listed below.	155060	at the ap	huohutare	periormance stand	aro
	Reference any narratives written in conjunction with this in	enertion	at the ar	nnonnista	nerformance stand	and
	listed below.	Spection	av viie ap	ibi ohi 1846	per rormance stand	ai u
	Provide a brief status report for all pending enforcement a	artions.	permit co	nditions.	Division Orders	and
	amendments.	,	p cc	,	21,1210,1 0,00,0	4,770
	EV	ALUATE	D N/A C	COMMENTS	S NOV/ENF	
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]	
	SIGNS AND MARKERS	[ ]	[ ]	<u>[ ]</u>	[ ]	
	TOPSOIL	[XX]	[ ]	[ XX ]	[ ]	
4.	HYDROLOGIC BALANCE:					
a.		[XX]	[ ]	[ ]	[ ]	
	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[ X X ]	[ ]	
	OTHER SEDIMENT CONTROL MEASURES		[ ]	[XX]		
	WATER MONITORING	[ ] [ ]	[ ]			
	EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]	
	EXPLOSIVES		<u>[ ]</u>	[ ]		
ь.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	<u>[ ]</u>			
/.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE	[XX]	<u>i</u>	<u>[XX]</u>	[ ]	
٥.	PROTECTION OF FISH, WILDLIFE AND	<u> </u>	<u>L J</u>		<u>L J</u>	
٦.	RELATED ENVIRONMENTAL VALUES	r n	r n	r 1	r 3	
10.	SLIDES AND OTHER DAMAGE	1 3	<u> </u>	1 1	<u>r                                    </u>	
11.	CONTEMPORANEOUS RECLAMATION	1 1	+ +	+ +	<u>r , , , , , , , , , , , , , , , , , , ,</u>	
	BACKFILLING AND GRADING	1 1	1 1	<u> </u>	<u> </u>	
	REVEGETATION	<del></del>	<del>                                     </del>		1 1	
14.	SUBSIDENCE CONTROL	1 1	1 1	1 1	<del>† †</del>	
	CESSATION OF OPERATIONS	[ ]	<u>i i</u>	<u>; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; </u>	<u> </u>	
16.	ROADS:	<del></del>	<del></del>	<del></del>	<del></del>	
a.		[ ]	[ ]	[ ]	[ ]	
	DRAINAGE CONTROLS	[ ]		<u> </u>	<u> </u>	
17.	OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ] [ ]	
19.	AVS CHECK (4th Quarter-April, May, June)	[ ]	[ ]	[ ]	[ ]	
	AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]	
21.	BONDING & INSURANCE	[ ]	[ ]		[ ]	

## INSPECTION REPORT (Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005 DATE OF INSPECTION: July 13, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

#### 3. Topsoil -

The expansion to open the coal storage yard at the track/coal train loadout facility has increased the topsoil storage at the site. The company was in the process of moving the material to the storage facility.

#### 4b. Sediment Ponds and Impoundments -

The upper sediment pond at the mine site will be in the process of being closed out. The company tried earlier in the month to clean the pond but the new removal process did not work.

The lower pond at the loadout facility was being expanded to facilitate the increased size of the coal storage yard.

#### 4c. Other Sediment Control Measures -

There were two locations that straw bales would need to be changed out due to wildlife eating the bales.

#### 7. Coal Mine Waste/Refuse Piles/Impoundments -

It is predicted that all the refuse material for this year has been brought to the refuse pile. The material will be compacted shortly.

<u>Note:</u> This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to:	Coastal States Energy/Utah Fuel, Keith Zobell
Mailed to:	Bernie Freeman (OSM)
Given to:	Joe Helfrich (DOGM)
Filed to:	Price Field Office
Date: July	14. 1993

Inspector's Signature and Number:

Sternen J. Demczak

#39